SECTION

## CLINTON COUNTY REMONUMENTATON SOUTHEAST CORNER OF SECTION 34 AND SOUTHWEST CORNER OF SECTION 35, T6N-R1W LAND CORNER RECORDATION CERTIFICATE 004 PAGE 3 | 2

Filing Requirement of Act 74, Mich. P.A. 1970

Clinton (County)	Located in:	Corner Code #
1. Public Land Survey	T_6N_R_1W_ T	1-13
2. Property Controlling In Section	STR STR	
Miscellaneous     Property in Sec.     Lot No	STR STR Recorded Plat	

I, Mark L. VanRaemdonck, in a field survey on January 27, 1998, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- Original: Lucius Lyon 1826 Monument: Wood post Accessories: Elm 7 N65°E 59 West Oak 24 N33°W 45
- Larry Bryan, Certified Survey Recorded Liber 5, page 43 2/9/95

  Monument: Set ½ \* bar with cap in centerline road

  Accessories: Nail & tag West side 18" Oak N30°W 32.15'

  Found \*Stephens\* tag North side 36" Oak S75°W 71.34'


  Found 1\* square bar at NW corner, Section 2, T5N-R1W, West 80.27' 2.
- Larry Bryan, L.C.R.C. Recorded Liber 2, page 367 2/26/61 3. Monument: Set 1/2 \* bar & cap at recorded falling distance on township line Accessories: Same as No. 1 above

RECORDED

DEC 28 3 48 PM '98

REGISTER OF DEEDS CLINTON COUNTY, MICH. Canal . which

Register of Deeds Stamp & File Number





(continued on reverse)

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: Found rerod and cap #25832 as referenced in No.'s 2, 3, 4 and 5 above. I accepted this location as the original corner position based on the best available evidence. There is no apparent conflicting monumentation.

C. Description of monument for corner and accessories to perpetuate locating the position of the corner:

Set a Standard Clinton County Remonumentation Monument, being a 2 ½" diameter steel tube, 30" long with brass cap stamped P.S. 24622 and a break away magnetic base, at the location described in Section B above. The Monument is witnessed by the following accessories:

\$50°E 42.01' Fnd. N&T #25632 in NE face 18" Walnut \$70°E 66.81' Set N&T #24622 in N. face 24" Walnut \$70°W 71.25' Stephens N&T N. face 48" Oak N30°W 31.94' Set N&T #24622 SW face 30" Oak N89°18'02"E 2641.86' Remon. monument at J-13, T6N-R1W \$89°42'04"W 2643.09' Remon, monument at H-13, T6N-R1W

Bearings to corners J-13 and H-13 are based on solar observations taken near the SE corner of Section 36, T6N-R1W

Signed by Mark L. Van Pa Surveyor's Michigan License No.

Date 5EPT. /, 1998

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYO

REVISED MAY 14, 1975 REVISED JAN, 1983

APPROVED BY CLINTON COUNTY PEER GROUP 7/29/98 DATED.

REMORDINENTATION

FED 1 8 1899

## SECTION

A. Description of original monument and accessories and/or subsequent restoration:

(continued from front)

LIDER 004 PAGE 313

Larry Bryan, Certifled Survey Recorded Liber 3, page 972 8/14/90 Survey dated 3/31/86 Monument: Found ½ \* bar & cap in centerline road Accessories: Same as No. 1 above.

Larry Bryan, Certified Survey Recorded Liber 4, page 705 11/3/93

Monument: Found bar & cap in centerline Cutter Road on tree line North.

Accessories: Found Nail & tag N. side 40' Oak \$75°W 71.29'

Set N&T 25832 W. side 18" Oak N30°W 32.15'

Set N&T 25832 South side 18" Walnut \$55°E 41.95'

Northeast corner Section 3, T5N-R1W, Bath Township West 80'