SECTION

CLINTON COUNTY REMONUMENTATON SOUTHEAST CORNER SECTION 35 AND SOUTHWEST CORNER SECTION 36, T6N-R1W LAND CORNER RECORDATION CERTIFICATE 004 PAGE 3 | 5

Filing Requirement of Act 74, Mich. P.A. 1970

Clinton (County)	Located in:	Corner Code #
1. Public Land Survey	T <u>6N</u> _R <u>1W</u> T <u>R</u> TR T R	<u>K-13</u>
Property Controlling In Section Miscellaneous	STR STR STR	
Property in Sec. 4. Lot No 5. Private Claims	Recorded Plat	

I, Mark L. VanRaemdonck, in a field survey on January 27, 1998, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Original: Lucius Lyon, D.S. February 1826 1. Monument: Wood post Accessories: Aspen 10 N31°W 6

В. Cak 14 N44 1/2 °E 50

James Stephens, L.C.R.C. Recorded Liber 1, page 775 4/25/74 Monument: Found 1/2" iron rod Accessories: S28°E 82.85' to the Northwest corner of a 1 story frame house #9002 Survey tag in the East side of a utility pole, \$27°16W 42.81 Survey tag in the East side of a 30" Oak tree S68°22'W 66.90'

- James Stephens, Certified Survey Recorded Liber 1, page 459 4/25/74 3 Monument: Found 1/2 " iron rod Accessories: Same as No. 2 above.
- Marvin Fouty, Certified Survey Recorded Liber 4, page 199 12/28/90 Monument: Not given. Accessories: None given.
- B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: Found 1/2 " rod. As referenced in No. 2 above. I accepted this location as the original corner position based on the best available evidence. Found no conflicting monumentation.
- C. Description of monument for corner and accessories to perpetuate locating the position of the corner. Set a Standard Clinton County Remonumentation Monument, being a 2 ½" diarneter steel tube, 30" long with a standard brass cap stamped P.S. 24622 and a breakaway magnetic base, at the location described in Section B above. The monument is witnessed by the following accessories:

NW corner foundation house #9002 S25°E NW corner garage 94.85 South

Pierson tag in E. face util. pole 42.71 S25°W N&T #25832 in S. face util. pole N65°W 58.92

\$69°39'58"W 77.88' Remon. monument at corner K-1, T5N-R1W N89°23'56"E 2643.82' Remon. monument at corner L-13, T6N-R1W

Bearings to corners K-1 and L-13 are based on a solar observation taken near the Southeast corner of Section 36, T6N-R1W.

Signed by Mark L Vanslandowsk Surveyor's Michigan License No.

Date <u>SEPT 1,1998</u> ATE BOARD OF LAND SURVEYORS

JAN 18, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

APPROVED BY CLINTON COUNTY PEER GROUP DATED

RECORDED

DEC 28 3 48 PM '98

REGISTER OF DEEDS CLINTON COUNTY, MICH. Cons woolen

Register of Deeds Stamp & File Number



