SURVEY & REMONUMENTATION

MAR 2 1 1997

Surveyor's Michigan License No. 24622

COMMISSION

REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in			Victor Township			RE	CORDED
Clinton		Located In:	Corner Code #				
(Cou	nty)					Nov 19	10 зэ АН '9
1. Public Land Su	ırvey	T <u>6N R 1W</u>	M-10			REGIST OUTFOR	PET TEEDS 1 Witchiell. Wording
		T R TR		l 1	LIBER 4, PAGE		conveg.
2. Property Contro	olling S	TR		_			
in Section 3. Miscellaneous	S	TR TR		Re	gister of Deed	s Stamp &	File Number
Property in Sec				_	-		
4 Let No	D	and the t		_	ABCDE	FFGH	I J K L M
I, Mark L. VanRae requirements of P., above were in conmanual of survey ir Management or by lines 3, 4 and 5 a Surveyors or by a monumented, recov. NOTE: Not mormay be recorde A. Description of of the control of th	emdonck, in a field A. 74, Michigan of the formance with restructions of the adecree of a Colored found as expected, found as expected, found as expected found as expected found as expected found for this cert original monument. Wood post es: Ash 5 do 6 fourty found a 3/4" pip South &	Ild survey on July 22 P.A. of 1970, the corregulations and rules United States Depar Court of Law and/or to Informance with the rule of Law; established Expressed below: ers, all in the san ificate. t and accessories and S67½°E 7 N14°W 20 397, 1/14/86. e & cap #2585 fence West		that under es 1 and 2 he current a of Land entioned in rd of Land tented, re- n: ohn A. Selleck, s Monument:	2 6 5 3 4 7 8 5 5 6 18 17 7 7 7 8 19 20 9 10 30 29 11 12 31 32 13 13 13 14 15 15 15 15 15 15 15 15 15 15 15 15 15	91.40' Fnd. 659, 4/9/84 nce corner p Set 3/4" pipe Set 2.35' 15°W 8 90'	-23 - 24 - 25 - 35 - 36 - 35 - 36 - 36 - 36 - 36 - 3
ound 3/4" pipe 3 fe	et long as refere	nced in No. 2 and 2 a	plied in restoring or reesta bove. This pipe was driver ed on the best available or			ose Found :	on conflictes
Description of mive could not remove could not remove thin to county Monu tamped "24622" and 40°W 6.05' Seouth 14.70' Se 85°W 9.33' Se	onument for corn e the stump nor o ument. The Monu d is witnessed by et N&T #24622 ir et N&T #24622 ir	er and accessories to could we cut through i ment is situated 1.00 the following access i W. face 10" Ash	perpetuate locating the po	osition of the co	ner: d stump in which tual corner locatio	we installed	
he actual corner too 40°W 6.95' Se outh 14.00' Se 85°W 10.20' Se 15°E 8.00' Se	cation is witnessed N&T #24622 in the N&T #24622	ed by the following acc W. face 10" Ash W/ face 12" Ash	cessories:		M/ VANRA SUR	ARK L. JEMDONC' AND Veyor No. 1622	William ** * *
Signed by	ren 4. Km	of many land			/		

3/21/16 FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS JAN 18, 1971]
REVISED MAY 14, 1975
REVISED JAN., 1983

196

APPROVED BY
CLINTON COUNTY PEER GROUP
DATED 7/17/96