

i	
MAR 2 1 1997	REMONUMENTATION
William Language	SECTIONS 16 & 17, OLIVE TOWNSHIP
COMMISSION	LAND CORNER RECORDATION CERTIFICATE
	Filing Requirement of Act 74, Mich. P.A. 1970

for conners in	we corded
Clinton Localed In Comer Co	nde#
(Comb) 1 Dublie Land Survay T ON R 2W	Oct 11 8 53 AN 196
1 18	cultor our or or
<u> </u>	Gunope anticinion.
T_R	Carnets Wording
2. Property Controlling	
3. Miscellaneous S TR	LIBER 4, PAGE 168
Property in Sec. S TR	Register of Deeds Stamp & File Number
	· · · · · · · · · · · · · · · · · · ·
4. Lot No, Recorded Plat	ABCDEFGHIJK L
5. Private Claims	A B C D E F G H I J K L N
	2 - 6 - 5 3 2 1 -
	3
I, <u>Arden S. Pierson P.S.</u> , in a field survey on <u>August 13</u> , 19 requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentione	sdin line≰1 and 2 above were in
conformance with regulations and rules therefore as required in the current m	anual of survey instructions of the
United States Department of the Interior, Bureau of Land Management or by that the corner points mentioned in lines 3, 4 and 5 above were in conformal	nce with the rules of the Michigan
Board of Land Surveyors or by a Decree of a Court of Law; established	ed, re-established, monumented,
recovered, found as expressed below:	8 19 20 21 22 23 24
NOTE: Not more than 2 comers, all in the same town and range, ma	ry be recorded 9 1
on this certificate.	10 -30 -29 -29 -29 -25
	12 31 32 33 3 3 3 3 3 3 3 3 3 3 3 3 3 3
	13 Land Land Land Land Land Land Land Land
A. Description of original monument and accessories and/or subs	equent restoration.
♦ Original survey by Hervey Parke, DS, 1826. Set 1/4 Sec	tion Post, witnessed by: Tamarack 7" - S5()°E - 2 links; Tamarack 7" -
N19-½°E - 11 links.	72. Liber 1, pages 419-420. A 3/4" iron pipe was set in the centerline
of the section line road (Loomis Road) and on a projection	of an old fence East of the corner. Witnessed by:
Survey tag in the E. Side of a Utility Pole - N77°0:	3'W - 312.20'
Survey tag in the top of a fence post - N75°52'E -	29.20
Survey tag in the top of a fence post - S89°46'E - 2 The bearing of the section line north of the corner	s North.
	(OVER)
B. Description of corner evidence found and/or method applied in	restoring or reestablishing corner:
•	1 1
Found 1/2" rod. (Also found buried, boiler tube culvert.) A	eccepted as a careful and faithful reestablishment of the position of the
original corner.	
+C., Claudand Clinton County Manuscrapt	MARTHAMAS
*Set Standard Clinton County Monument.	AND OF MICHIGAN
3	And State of the s
.	* ARDEN 8. * 1
C. Description of monument for corner and accessories establish	# PIERSON **
1/4 Corner Common to Sections 16 & 17	58.20'
*Sct Standard Clinton County Monument	13039
Nail & tag #13039 in W. side Telephone Pole - N11°E - 2	08.20°
Nail & tag #13039 in N. side Pole Anchor Post - S85°W - Nail & tag #13039 in SW side Power Pole - S30°E - 52.48	THE TUESDAY TO THE PROPERTY OF
Nail & tag #13039 in NE Corner 6"x6" Gate Post - S50°E	- 32,92'
,	
*Standard Clinton County Monument is a 21/2" dia. Steel to	ibe 30" long with a stamped brass cap and a
breakaway magnetic base.	· de
Signed by Uhn Situan	Date
10000	
Surveyor's Michigan License No. 13039	
ANNOOP O BY	Y

- ♦ Certificate of Survey by James Stephens, PS, #16053, dated May 25, 1973, Liber 1, page 328.
- ♦ Certificate of Survey by LaVerne Hendryx, PS, #3276, dated June 20, 1973, Liber 1, page 342.
- ♦ Certificate of Survey by James Stephens, PS, #16053, dated July 17, 1973, Liber 1, page 348.
- ♦ Certificate of Surveys by Ronnie Lester, PS, #18998, dated May 1989, Liber 3, pages 371-374. 5/8" rerod, witnessed by:
 Stephens nail & tag in top post 97° az. 28.4'
 Stephens nail and tag in top post 84° az. 29.4'
 Set nail and tag in N. Side fence post 265° az. 30.5'
 Set nail and tag in West side Utility pole 150° az. 52.3'

Set nail and tag in West side North gate post - 130° az. - 32.8'

. .):