SURVEY & REMONUMENTATION

FEB 0 2 1998

REMONUMENTATION

SECTION

SECTION 32, OLIVE TOWNSHIP

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

LIBER OO4 PAGE 233

For corners in Clinton (County)	Located In:	Corner Code #			R	ECOR	DED		
1. Public Land Survey	T_6N_R_2W TR TR TR	E-13		Oct of	t 17 Ultuk Szacis	9 2	o AM	'9 7 ir.	
 Property Controlling in Section Miscellaneous Property in Sec. 	S T R S T R S T R S T R	Reg	Cliffich of Deeds Stamp & File Number						
4. Lot No, I	Recorded Plat		1 '	4 B	C D	E F	э н	ΙJΚ	i. M
			2	6	5	4	3	2	1
t, Arden S. Pierson, PS , in a field survey on July 23 19 97 , do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points					8	9	10	11	12
mentioned in lines 1 and required in the current m	5 6 7	18	17	16	15	14	13		
Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented					20	21	22	23	24
re-monumented, recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded				30	29	28	27	26	25
on this certificate.			11 12 13	31	32	33	34	35	36
			. •		4	0			

- Description of original monument and accessories and/or subsequent restoration:
 - ◆Original survey by Hervey Parke, DS, 1826. Set post corner to Section 32 & 33, witnessed by: W. Oak 15" - N72°E - 39 links; Maple 7" - N79°W - 29 links.
 - ♦Survey by Charles Hollister, County Surveyor, January 28, 1890. Found a stone set to mark the corner of sections 32 and 33 on range line and one witness tree W. Oak $30'' - S5^{\circ}E - 67$ links.

(over)

APPROVED BY CLINTON COUNTY PELR GROUP UAILU _8/20/97

PROFESSIONAL

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1/2" rod over pointed stone down 30" below asphalt. Accepted 1/2" rod as a careful and faithful perpetuation of the position of the original corner.

Left storm monument box.

(Closing Corner for T5N, R2W, is 29.61' west,

Description of monument for corner and accessories established to perpetuate locating the position of the cytenson professional surveyor No.

13039

- N53°E - 46.52'

70FESSION FROMESSION FRO Left stone in place and placed Standard Clinton County Monument over stone in WAR OF MICHIGAN

Southeast Corner, Section 32		SURVEYOR
*Standard Clinton County Monument and	monument bo	ox 10039
SE Corner Concrete Fence Post - N02°F	i - 30.96'	The second secon
Nail & tag #13039 in NW side Power Po	ole - N53°E	- 46.52' N. POFECCIONAL MA
Nail & tag #13039 in East side 21" Hi	.ckory - S25	"W - 52.76'
Nail & tag #13039 in North side 14" C)ak - S68°E	- 109.91'
To D-13, T6N, R2W, N89°39'03"W. 2639.		
To E-13, T6N, R2W, S89°49'00"E. 2638		solar observations.
*Standard Clinton County Monument is a 212"		
brass cap and a breakaway magnetic base.		•
(a, a, a) .		
Signed by War Yilliam	Date	July 29, 1997
Surveyor's Michigan License No. 13039		FORM APPROYED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 10
Ouveyor's interngant Election from		DEVISED MAY 14, 18:
		ADADTED CAR WORK RECORD MAINTE TO

◆Clinton County Surveyor Field Notes -- Witnessed by W. Oak 30" - S5°E - 67 links.

◆LCRC by Richard W. Steadman, PS, #11370, dated March 8, 1976, Liber 2, Page 120. Dug hole in Cutler Road opposite fence line North and just below the surface, found a pointed stone. Excavation had to be made very carefully because of buried telephone cable passing near the stone and 6" below the surface. Witnessed by:

Telephone pole - S51°E - 46.41' 8" Ash in clump - South - 45.25' 12" Hickory - S25°W - 52.55'

LIDER OOL PAGE 234

性病症 排作 唐门斯

◆Certificate of survey by Fred N. White, PS, #12034, dated November 22, 1978, Liber 2, Page 134. ?