SURVEY & REMONUMENTATION

MAR 2 1 1997

REMONUMENTATION SECTION 6, BENGAL TOWNSHIP

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

		- 1		
RE	001	J D	Ŀ	'n

For corners in COMMISSION

Clinton Located In: Corner Code #	Oct 11 8 53 AH '96
1. Public Land Survey T_7N R 3W T_7N R 4W T_8N R 3W T_8N R 4W M-13 T_8N R 4W M-13	Clinton of the Ment of the Control o
2. Property Controlling S T R	LIBER 4, PAGE 172
Property In Sec. ST_R	Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat 5. Private Claims	B C D E F G H I J K L H
	3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3
requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above we conformance with regulations and rules therefore as required in the current manual of survey instructions. United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law a that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Mic Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monume recovered, found as expressed below:	of the . 5
NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate.	9
	11
A. Description of original monument and accessories and/or subsequent restoration:	13
 ◆ Original survey by Robert Clark, DS, dated February 1831. West on S. Bound end of 6 miles, 5.98 set post. Witnesses: B. Ash 16" - S65°E - 56 links; B. Ash ◆ GLO Survey Corner Information by Joel Wright, DS, 1831. Stump witnessed ◆ Survey by R. H. Colburn, DS, 1884. Intersection corner of Essex, Lebanon, Dowitness. Witnesses: Elm 15" - N46°45'E - 149 links. ◆ Survey by Chas. Hollister, County Surveyor, dated May 25, 1887, Hollister Field Survey by Chas. Hollister, County Surveyor, dated June 20-21, 1889. No witnesses: Elm 15" - No witnesses: County Surveyor, dated June 20-21, 1889. 	by W. Oak 30" - N72°E - 68-1/2 links. allas and Bengal. Set stone and made new eld Book 6. No witnesses given. lesses given.
B. Description of corner evidence found and/or method applied in restoring or reestablish	
Found 1/2" rod and cap as set by Mark VanRaemdonck, PS. Measured North, Eastureyor Notes. Dug 3' x 3' hole 4' deep, found nothing. Accepted 1/2" iron and the position of the original corner. Set Standard Clinton County Monument.*	st and West. Agrees closely with County cap as a careful and faithful reestablishment of
(Found 16D nail, excavated 6' x 6' hole — no supporting evidence.)	AND OF MICHIER
(This corner is common to Bengal, Dallas, Essex and Lebanon Townships.)	ARIDEN S. PIERSON PROFESSIONAL
C. Description of monument for corner and accessories established to perpetuate locating Northwest Corner, Section 6 *Set Standard Clinton County Monument Nail & tag #13039 in NW side Power Pole - S28°W - 96.54' Stop Sign Post - N25°W - 95.92' Nail & tag #13039 in NW side Wood Anchor Post - N39°E - 35.96' Nail & Tag #13039 in NW side Wood Anchor Post - N48°E - 39.18' 8' South and 3' East of physical centerline roads.	
*Standard Clinton County Monument is a 2½" dia. Steel tube 30" long with a stabreakaway magnetic base.	amped brass cap and a
Signed by Chan Soften Date	August 24, 1996
Surveyor's Michigan License No. 13039	

LIBER 4, PAGE 173

♦ LCRC by Mark VanRaemdonck, PS, #24622, dated July 12, 1993, Liber 2, page 866, T8N, R4W, M-13. Restored corner location using measurements proporational to G.L.O. distances and the county surveyor distances between nearest known G.L.O. corners and fence locations. Set rerod and cap #24622. Witnesses:

N30°E - 33.91' - W. edge road sign post \$70°W - 49.57' - Top cen. S. End 18" CMP culv. \$20°E - 47.32' - Top cen. E. End 36" CMP culv. N60°W - 52.35' - Top cen. N. End 18" CMP culv.

♦ Clinton County field work. Found 16D nail in centerline Bauer and Kinley. Witnesses:

N30°E - 30.96' - W. edge road sign post \$70°W - 49.57' - Top cen. S. End 18" CMP culv. \$20°E - 47.32' - Top cen. E. End 36" CMP culv. N60°W - 52.35' - Top cen. N. End 18" CMP culv.