SURVEY & REMONUMENTATION

FEB 0 2 1998

REMONUMENTATION

SECTION

Surveyor's Michigan License No.

SECTIONS 13 AND 24, DUPLAIN TOWNSHIP LAND CORNER RECORDATION CERTIFICATE

LIBER 004 PAGE 213

Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

	Clinton (County)	Located in:	Corner Code #		(let l'i	7 9	18 A	Y ' 97			
	ic Land Survey	T 8N R 1W M-7 T R T R T R			REGIS LEK OF DEEDS DEANTON COUNTY, MICH. Cleanel, Wendleye							
in S 3. Mis	perty Controlling lection cellaneous perty in Sec.	STRSTRSTR		Register of Deeds Stamp & File Number								
4. Lot	No,	Recorded Plat		A	B (O D	E F (:: 3 H I	i J K	(L I		
b. Priv	ate Claims			$-\frac{1}{2}$	6	5	4	3	2	T 1		
				3					<u> </u>	 ' -		
I, Wendy A. Papineau , in a field survey on June 1997 , do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5				, 4	7	8	9	10	11	12		
				6	18	17	16	15	14	13		
above w Court of expresse	f Law; established	with the rules of the Michigan Boar I, re-established, monumented, a	d of Land Surveyors or by a Decree of a re-monumented, recovered, found as	8	19	20	21	22	23	24		
•		2 corners, all in the same towi	n and many a marcha variable	10	30	29	28	27	26	25		
HOTE.	on this certifica		n and range, may be recorded	11								
A. D	escription of orig	inal monument and accessorie	es and/or subsequent restoration:	12 13	31	32	33	34	35	36		
<u>M-7</u>	Standard Section Corner, Section 13 & Section 24, T8N-R1W Wood post placed by Robert Clark Jr., D.S. Jan.26, 1831 S 23 W 20 lks (13.20') 15" Beech N 20 W 6 lks (3.96') 10" Lynn Unrecorded survey by V.P.McMahon, Aug. 27,1978,					APPROVED BY CLINTON COUNTY PEER GROUP DATED						
		references given vey by James Porter, E.D.	T Oct 1986		·		87	-3 - 100				
		14-F (rev) No monument or								٠,		
B. D	escription of corn	er evidence found and/or meti	hod applied in restoring or reestablish	ing corne	er:				•			
<u>H-7</u>	Standard Section Corner, Section 13 & Section 24, TBN-RIW James Porter when running the East line of Sections 13,24,25,36, single proportioned form M-13 to M-5, in search for reliable positions for government corners. We found a 1/2" rod w/cap #19003 in monument box 3.5' E. of the centerline of Meridian Road and at the centerline of Mead Road, per Porter's field notes.											
	2 Drain fit we	ell with this call (G.L.O.	'. Measurements to the centerli 26.00 ch = 1716' Meas. = 1718' (Calc. split = 1324.24' Occup.). Also	, occ	see & supati	Clint on at	on No	>.			
	from the N 1/4 Property irons	Cor., Sec.24, T8N-R1W to found from the McMahon Su	on the McMahon & Porter surveys the NW Cor., Sec. 24, T8N-R1W a arvey are 2.7' E. of their recor -S 1/8 line (1311') fit the spli	nd Porte d distan	r mea	sured om sa	2621. id N 1	15	r.			
	Upon review of all information, the existing 1/2" rod is determined to be the best available evidence of the position of the original corner.											
	Approved by th	e joint Clinton/Shiawassee	County Remonumentation Peer Re	view Gro	up Au	igust	13, 19	97				
C. D	escription of mon	ument for corner and accesso	ries established to perpetuate locatin	g the pos	sition	of the	corner		٠.			
<u>H-7</u>	Replace 1/2" r with a magnet, S30E 83.32' Se S30W 57.76' Se N60W 57.08' Se	in existing box. Et PK w/tag #39096 W. fc P/ Et N&T #39096 SE fc 24" Elm Et PK w/tha #39096 S. fc P/	Monument, 2"x30" steel pipe, 3 1 /p	/4" bras	s cap	and j		F M / C	WANTE TA			
	N40E 36.63' To	Meridian at CL Mead p center Bell riser edge of N. leg double arr	cow sign "<->"			I -1	PRO	APINE/ ESSIÓ	NAL	0		