SURVEY & REMONUMENTATION

MAR 2 1 1997

REMONUMENTATION SECTION 6, BENGAL TOWNSHIP

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

2.

For corners in	ļ. •	•	*						
Clinton (County)	Located In:	Corner Cod	de#	-		0	let 11	8 53 AH 19	J.
1. Public Land Survey	T_7N_	R3W R4W R3W	A-1 M-L A-13			(REGISTE CHITCH C	LL SEEDS	
Property Controlling in Section Miscellaneous Property in Sec.	T <u>rn</u> ST	R_4W R R R	M-13	LI		PAGE 17	12	File Number	
A.I. Abb	earded Dist								
4. Lot No, Rec 5. Private Claims	corded Frat				B C	D E E	GII	1 J K L N	1
I, Arden S. Pierson P.S. requirements of P.A. 74, Micronformance with regulations United States Department of that the corner points mention Board of Land Surveyors of	and rules therefore as required interior, Bureau of Landanian lines 3, 4 and 5 abo	orner points mentioned uired in the current ma id Management or by a ove were in conforman	d in fines 1 and 2 : nual of survey Insti decree of a Court : ce with the rules of	above were in ructions of the . of Law and /or f the Michigan	3 - 7 - 5 - 18 - 7 - 19 - 7 - 19 - 7	B	515	—11——12— —14——13—	
recovered, found as expresse	ed below:			monumentes,	8 —19—	20 -2	122-	2324	$\left \right $
NOTE: Not more than 2 on this certificate.	comers, all in the same t	town and range, may	be recorded		10 - 30 - 11	292	827	26 -25	
					12 -31-	323	3- -34-	35 35	
A. Description of original	I monument and acces	sories and/or subse	quent restoratio	n:	,				
◆ Original survey by lend of 6 miles, 5.98 se ◆ GLO Survey Corne ◆ Survey by R. H. Cowitness. Witnesses: E ◆ Survey by Chas. He ◆ Survey by Chas. He	et post. Witnesses: Ex Information by Joel olburn, DS, 1884. Int Elm 15" - N46°45'E - ollister, County Surve	B. Ash 16" - S65° I Wright, DS, 183 Iersection corner o - 149 links. evor. dated May 2	E - 56 links; B 1. Stump witr of Essex, Lebar 5. 1887, Holli:	nessed by W. G non, Dallas an	30°E - 20 Oak 30" - id Bengal. ik 6. No v	N72°E - (Set stone	68-½ links and made	J.	
	revidence found and/o		**						
Found ½" rod and cap Surveyor Notes. Dug the position of the ori	2' v 3' hole 4' deen	found nothing. A	ccepted ½~ iro	on and cap as a	West. Ag a careful a	rees closel and faithfu	y with Co I reestabli	unty shment of	
(Found 16D nail, exce	avated 6' x 6' hole —	- no supporting ev	idence.)			HARRIAN	F MICHIO	Marke.	
(This corner is comme	on to Bengal, Dallas,	, Essex and Lebar	non Townships	i.)	***		DEN S. ERSON		
C. Description of monun Northwest Corner, S *Set Standard Clintor Nail & tag #13039 in Stop Sign Post - N25 Nail & tag #13039 in Nail & Tag #13039 i 8' South and 3' East o	NW side Power Pol NW - 95.92' NW side Wood And nNW side Wood An	chor Post - N39°E schor Post - N48°	E - 35.96'	locating the pos	sition of the	corner;SU	ESSIONAL RVEYOR No. 13039 ESSION NO.	SO LAND MAN TO SERVICE MAN TO SERVIC	
*Standard Clinton Co breakaway magnetic	bunty Monument is a base.	12½" dia. Steel tu	be 30" long wi	ith a stamped	brass cap	and a		÷	
Signed by	n Soleun		`}	Date		August 24	, 1996		
Surveyor's Michigan Lice	ense No	13039	1						
· · · · · · · · · · · · · · · · · · ·									

♦ LCRC by Mark VanRaemdonck, PS, #24622, dated July 12, 1993, Liber 2, page 866, T8N, R4W, M-13. Restored corner location using measurements proporational to G.L.O. distances and the county surveyor distances between nearest known G.L.O. corners and fence locations. Set rerod and cap #24622. Witnesses:

N30°E - 33.91' - W. edge road sign post

S70°W - 49.57' - Top cen. S. End 18" CMP culv.

S20°E - 47.32' - Top cen. E. End 36" CMP culv.

N60°W - 52.35' - Top cen. N. End 18" CMP culv.

♦ Clinton County field work. Found 16D nail in centerline Bauer and Kinley. Witnesses:

N30°E - 30.96' - W. edge road sign post S70°W - 49.57' - Top cen. S. End 18" CMP culv. S20°E - 47.32' - Top cen. E. End 36" CMP culv. N60°W - 52.35' - Top cen. N. End 18" CMP culv.