STATE OF MICHIGAN DEPARTMENT 0F NATURAL RESOURCES

LAND CORNER RECORD

		<u>Crawford</u> COUNTY	
		T <u>25 N</u>	R _2_W
DESCRIPTION OF CORNER	E 1/4 corner, Sec.	23	
CORNER MONUMENT	Set Dept. Monument		
DATE MONUMENT PLACED AND	WITNESSED8	-5-71	
WITNESSES TO CORNER	. <u>16" R. Pine</u>	N 40 E	80.51
N .	6" R. Pine	N 38 W	 58.9¹
23	Concrete Monument	East	33.0'
	AND		
CIRCLE CORNER REGISTE	RED		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Previously established by G. D. Henning, but corner point had been removed, by unknown.

Recovered Henning location from his witnesses and concrete monument.



SURVEYOR'S SEAL

SIGNED

REGISTERED LAND SURVEYOR

DISTRIBUTION:

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing

R 4047 Rev. 10/68