

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD


CRAWFORD COUNTY  
T 25 N R 2 W

DESCRIPTION OF CORNER 1/4 corner common to Sections 14 - 23

CORNER MONUMENT Set Dept. Monument

DATE MONUMENT PLACED AND WITNESSED 5-19-71

WITNESSES TO CORNER..... 7" J. Pine N 50 W 4.4'



9" J. Pine S 25 E 37.5'

10" J. Pine N 10 W 32.5'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Found square post (rotted off at ground level) and both G. Hennings NBTs in place in good condition. Henning says he found NW USBT & depression at location for SE USVT. Part of Bole of J.P. Tree still on ground for NW USBT showing axe marks and evidence of over growing for both faces.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

*Levinth Hennings*  
REGISTERED LAND SURVEYOR #10068

DATE

5-26-71

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68