## STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

## L'AND CORNER RECORD

				CRAWFORD			COUNTY	
				T _25	<u>. N</u>	R.	2	W
DESCRIPTION OF CORNER		W 1/16 corner co	ommon to Se	ctions	13 & 24			
CORNER MONUMENT		Found 3/4" pipe	(by Hennin	g)				
DATE MONUMENT PLACED AND	WITN	ESSED5-	-18-71					
WITNESSES TO CORNER	•							
N	*	7" Tamarack	S 14 1	₩ 7.51			! 	
13	*	8" Cedar	S 80 1	<u> </u>			23.7	ı 
	AND	* G. D. He	enning BTs		· · · · · · ·		·	
CIRCLE CORNER REGISTER	ED							

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found with a pipe set by G. Henning.

SURVEYOR'S SEAL

DISTRIBUTION: SIGN

SIGNED LUMB SILLING
REGISTERED LAND SURVEYOR

E 5-25-73

**#10068** 

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing