STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

		CRAWFORD	COUNTY
		T25_N	R2W_
DESCRIPTION OF CORNER	N 1/4 corner, Secti	ion 14	
CORNER MONUMENT	Set DNR Monument		
DATE MONUMENT PLACED AND	WITNESSED	7-16-71	
WITNESSES TO CORNER	•		
N	36" W. Pine	S 30 E	106.1'
	8" J. Pine	S 75 W	128.51
	AND		
CIRCLE CORNER REGISTE	RED		DECTORED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner restored by proportionate measurement, M.P.O.L. between section corners. No evidence of a previous corner.



SURVEYOR'S SEAL

DISTRIBUTION:

EGISTERED LAND SURVEYOR

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing

R 4047 Rev. 10/68