

✓

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 25 NR. 3 W.

Grandford COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 9 & 10

DESCRIPTION OF CORNER MONUMENT 1" Pipe in road

WITNESSES TO CORNER 12" J. Pine - S 30 W - 54 Links

9" J. Pine - N 10 E - 36 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

**This corner was found by Forestry Division survey crew, while making a partial resurvey of this Township. One original B.F. still in place, in good condition.**

**Corner was placed and witnessed July 15, 1954.**

SURVEYORS SEAL

SIGNED Alan C. [Signature] DATE 9/20/54  
REGISTERED LAND SURVEYOR