MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T__25. NR_3_W__

			Crayford COUNTY
DESCRIPTION	OF	CORNER	1/4 Corner between Sections 14.6.23
DESCRIPTION	OF	CORNER	MONUMENT_1= Pipe with 4= Brass cap
WIT TNESSES	то	CORNER	10 J. Pine - 8 85 E - 36 Links
			_ 12*_Red_Oak = S 15_E22 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This cerner was established by Forestry Division survey crew, while making a partial resurvey of this Township. In the absence of any original evidence, corner was placed on line, midway between Section Corners.

Corner was placed and witnessed April 13, 1954.

SURVEYORS SEAL

SIGNED LAND SURVEYOR DATE 10/22/54_