

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD


CRAWFORD COUNTY  
T 25 & 26 N R 3 W

DESCRIPTION OF CORNER Section corner common to Sections 3-4-33-34

CORNER MONUMENT Set 1"x2' Pipe, below surface

DATE MONUMENT PLACED AND WITNESSED 4-27-71

WITNESSES TO CORNER..... 10" Oak N 56 W 66.9'



2" Pipe N 35 W 52.0'

12" J. Pine N 14 E 55.1'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Found 1/2" Re-rod, replaced with 1" Pipe 2' long. Corner located and used in previous surveys in this township.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

*Timothy Ostling*  
REGISTERED LAND SURVEYOR 10068

DATE

5/5/71

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68