

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. PA 1970

For Corners In: Crawford (County)	Located In	Corner Code #
1. Public Land Survey	T _____ R _____	_____
2. Property Controlling in Section	T _____ R _____	_____
	S 18 T 25N R 3W	12
	S 18 T 25N R 3W	13
3. Miscellaneous Property in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No: _____	Recorded Plat: _____	
5. Private Claims: _____		

Register of Deeds Stamp & File Number

I, Carl T. Kiiskila, in a field survey on May 28, 2003 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A	B	C	D	E	F	G	H	I	J	K	L	M
1												
2	6		5		4		3		2		1	
3												
4	7		8		9		10		11		12	
5												
6	18		17		16		15		14		13	
7	•	•										
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												

A. Description of original monument and accessories and/or subsequent restoration:

12-Marvin E. Myers P.S. #31600 set a 1/2" X 18" steel bar for the Northwest corner of the Southwest quarter of the Southeast quarter of section 18, in February of 1991.

13- Marvin E. Myers P.S. #31600 set a 1/2" X 18" steel bar for the Northwest corner of the Southeast quarter of the Southeast quarter of section 18, in February of 1991.

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

12- Found and accepted 1/2" iron rod with P.S. cap #31600

13- Found and accepted 1/2" iron rod fitting Marvin E. Myers survey.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

12- Found 1/2" iron rod with P.S. cap #31600

13- Found 1/2" iron rod

Wit: 10" J. Pine N88°E 19.53'
5" J. Pine N03°E 33.58'
8" J. Pine N70°W 10.87'
5" J. Pine S13°W 18.08'
Carsonite Post North 1'±

Wit: 12" J. Pine N77°W 22.52'
10" J. Pine N34°E 12.18'
4" J. Pine S49°E 64.25'
6" J. Pine S13°W 56.73'
Carsonite Post North 1'±

Signed by:

Carl T. Kiiskila

Date:

7-1-03

Surveyor's Michigan License No.:

33981

