

MAR 29 2000

SECTION

LAND CORNER RECORDATION CERTIFICATE

_	Filing Requireme	ent of Act /4, Mich. P.A. 19	970
For corners in			STATE OF MICHIGAN
CRAWFORD (County)	Located In:	Corner Code#	CRAWFORD COUNTY RECORDED
Public Land Survey	TR T_ <u>25N_</u> R_ <u>4W</u> TR	B-13	17 AUG 99 12:29 P.H. SANDRA HODRE
Property Controlling in Section Miscellaneous	TR STR STR		REGISTER OF DEEDS
Property in Sec.	STR		Register of Deeds Stamp & File Number
4. Lot No, Reco			1 A B C D E F G H 1 J K L M 2 - 6 - 5 - 4 - 3 - 2 - 1
	, — <u>"</u>	IGE 06	3
I, Marvin E. Myers, in a field survey on April, 1999 do hereby state that under requirements of P.A. 74, 4 - 7 - 8 - 9 - 10 - 11 - 12 - Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with 5			
regulations and rules therefore as required in the current manual of survey instructions of the United States 6 18 17 16 15 14 13			
Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the			
corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered,			
found as expressed below:			9 10 30 29 28 27 26 25
NOTE: Not more than 2 c	orners, all in the same town an	d range, may be recorded	11
on this certificate.	•		$\begin{array}{c ccccccccccccccccccccccccccccccccccc$
A. Description of original	monument and accessories ar	nd/or subsequent restoration	1 :
G.L.O – 1839 John Brin	ık, D.S. Marcus S	chaaf 1940's	
Mon ~ Post Wit: 10" W. Oak N56°E	Mon - Iron	n Set	
11" Yellow Pine N			
B. Description of corner of Found Schaaf 1 ½" pipe in constand Crawford County M. C. Description of monum Mon: Standard Crawford County Wit: West edge of Carsoni Nail & tag SE side 4" Nail & tag SW side 5"	evidence found and/or method oncrete. Accepted pipe as the bestonument. ent for corner and accessories ounty Monument. te Post N52°E 19.50	st available evidence of the pos	ablishing corner: sition of the Original Corner. Replaced pipe with ocating the position of the corner:

STATE OF MICHGAN PROFE.
SURVEY
No.
31800
SOME
STATEMENT
STATEME

CRAWFORD COUNTY PEER GROUP APPROVAL

Missing E. Myen man Marvin E. Myers, P.S.

County Surveyor

Signed by

Surveyor's Michigan License No. 31600

Date <u>June 8, 1999</u>