## LAND CORNER RECORDATION CERTIFICATE

## FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

I. PUBLIC LAND SURVEY	T25, F	3. <u>4</u> ♥I	-3; I-5			
2. PROPERTY CONTROLL- ING IN SECTION	10 ,T. 25 N.	R. 4 P. 7				
3. MISCELLANEOUS PROPERTY IN SECTION -						
4. LOT NO, F	ECORDED PLAT					
5. PRIVATE CLAIMS				REGISTE	R OF DEEDS STAMP FILING NUMBER	AND
I, Kenneth J. Ost1 the corner points mentioned re-established, monumented, and rules therefore as requir Bureau of Land Managemen and 5 above were, in a field s as expressed below and in co Decree of a Court of law:	re-monumented, record in the current man tor by a decree of a courvey on	e were, in a field overed or restore nual of survey in court of law. Fu	survey on May and as expressed below structions of the Un rthermore, that the , found, recovered	w and in confo ited States Dep corner points to d, restored, esta		olished, ulations nterior, is 3, 4 blished
A. Description of original m	onument and accessor	ries and/or subse	quent restoration:			
			•	e.		
B. Description of corner evi		-	n restoring or re-esta	blishing corner:		
B. Description of corner evi  Found iron bar at  Found iron bar in  Set by standard s	road intersect	ion.	ted as corner.			
Found iron bar at Found iron bar in Set by standard s	road intersect N-S road appar urvey procedure	ion. ently accept for subdiv	ted as corner.	ons.		
Found iron bar at Found iron bar in Set by standard s  C. Description of monumen	road intersect  N-S road appar  urvey procedure  t for corner and acces	ently accept for subdiv	ted as corner.  ision of section  to perpetuate locati	ons. ng the position	of the corner:	
Found iron bar at Found iron bar in Set by standard s	road intersect  N-S road appar  urvey procedure  t for corner and access  Set  11"  1.75  10"	ently accept for subdiv	ted as corner.  ision of section  to perpetuate locati	ons. ng the position	of the corner:	b'to 71. 116.
Found iron bar at Found iron bar at Found iron bar in Set by standard s  C. Description of monumen  I-3 Left '3" Bar in place 3" Iron Fence Post N48°E Nail in Power Pole	road intersect  N-S road appar  urvey procedure  t for corner and access  Set  11"  1.75  10"	ently accept for subdiv	ted as corner.  ision of section  to perpetuate locati	ons. ng the position	of the corner:	b'to 71. 116.
Found iron bar at Found iron bar at Found iron bar in Set by standard s  C. Description of monumen  I-3 Left '3" Bar in place 3" Iron Fence Post N48°E Nail in Power Pole	road intersect  N-S road appar  urvey procedure  t for corner and access  Set  11"  1.75  10"	ently accept for subdiv	ted as corner.  ision of section  to perpetuate locati	ons. ng the position	of the corner:	b'to 71. 116.
Found iron bar at Found iron bar at Found iron bar in Set by standard s  C. Description of monumen  I-3 Left '3" Bar in place 3" Iron Fence Post N48°E 4 Nail in Power Pole N35 W 4	road intersect  N-S road appar  urvey procedure  t for corner and acces  Set  11"  1.75  10"  1:5.3	ently accept for subdiversories established in Spike over R. Pine R. Pine E of Center	ted as corner.  ision of section  to perpetuate location  1" iron bar  \$80°W 57.6  N60°W 59.2  N-S road	ons. ng the position	of the corner:	b'to 71. 116.
Found iron bar at Found iron bar at Found iron bar in Set by standard s  C. Description of monumen  I-3 Left '3" Bar in place 3" Iron Fence Post N48°E Nail in Power Pole	road intersect  N-S road appar  urvey procedure  for corner and access  11"  1.75 10"  15.3	ently accept for subdiversories established in Spike over R. Pine R. Pine E of Center 10068	ted as corner.  ision of section  to perpetuate location  1" iron bar  \$80°W 57.6  \$N60°W 59.2  N-S road	ons. ng the position	of the corner:	b'to 71. 116.
Found iron bar at Found iron bar at Found iron bar in Set by standard s  C. Description of monumen  I-3 Left '3" Bar in place 3" Iron Fence Post N48°E 4 Nail in Power Pole N35 W 4	road intersect N-S road appar urvey procedure t for corner and acces Set 11" 1.75 10" 1' 15.3	ently accept for subdiversories established in Spike over R. Pine R. Pine E of Center 10068	ted as corner.  ision of section  to perpetuate location  1" iron bar  \$80°W 57.6  \$N60°W 59.2  N-S road	ons. ng the position	of the corner:	b'to 71. 116.
Found iron bar at Found iron bar at Found iron bar in Set by standard s  C. Description of monumen  I-3 Left '3" Bar in place 3" Iron Fence Post N48°E Nail in Power Pgle N35 W  SIGNED BY  SURVEYOR'S MICHIGAN FOR STATE AND UNITED	road intersect  N-S road appar  urvey procedure  for corner and access  Set  11"  1.75 10"  1'  5.3  REGISTRATION NO  D STATES AGENCIE	ently accept for subdiversories established in the spike over in t	ted as corner.  ision of section  to perpetuate location  1" iron bar S80°W 57.6 N60°W 59.2 N-S road  DATE	ons.  Set Railr 4" R. Pir 3" R. Pir	of the corner:  7 coad spike in ne S68°E ne S32°E  ENNETH OSTLING LAND JRVEYOR (NA) 10068	b'to 71. 116.
Found iron bar at Found iron bar at Found iron bar in Set by standard s  C. Description of monumen  I-3 Left '3" Bar in place 3" Iron Fence Post N48°E Nail in Power Pgle N35 W  SIGNED BY  SURVEYOR'S MICHIGAN	road intersect  N-S road appar  urvey procedure  for corner and acces  Set  11"  1.75 10"  1'  5.3  REGISTRATION NO  STATES AGENCIE  CHIEF OF SURVEY I	ently accept for subdiversories established in the sories established established in the sories established	ted as corner.  ision of section  to perpetuate location  1" iron bar S80°W 57.6 N60°W 59.2 N-S road  DATE	ons.  Set Railr 4" R. Pir 3" R. Pir	of the corner:  7 coad spike in ne S68°E ne S32°E  ENNETH OSTLING LAND JRVEYOR (NA) 10068	b'to 71. 116.