## STATE OF MICHIGAN **DEPARTMENT** 0F **NATURAL RESOURCES**

## L'AND CORNER RECORD

		CRAWFORD	COUNTY
		т26	N R 1 W
DESCRIPTION OF CORNER	Ctr. 1/4 corner co	ommon to Section 3	
CORNER MONUMENT	Set 1"x24" Pipe		
DATE MONUMENT PLACED	AND WITNESSED 1-2	28-71	
WITNESSES TO CORNER	••••		
N Sec. 3	_6" Cedar	N 4 E	45.5'
0	4" Cedar	N 78 E	18.6'
	AND		
CIRCLE CORNER REGIS	STERED		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set at intersection of N-S & E-W 1/4 lines, during a survey of Section 3. Corner set to control subdivision and to mark state land boundary.

SURVEYOR'S SEAL

DISTRIBUTION:

10068

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing