

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


CRAWFORD COUNTY
T 26 N R 1 W

DESCRIPTION OF CORNER E 1/4 corner, Sec. 29

CORNER MONUMENT Left Conc. filled tile in place

DATE MONUMENT PLACED AND WITNESSED 8-30-71

WITNESSES TO CORNER..... 8" W. Oak N 06 W 26.4'



7" W. Oak N 70 E 23.2'

1" R. Pine N 78 E 9.0'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Concrete tile previously established by Houghton.

Recovered and accepted previous corner. Other surveys based on this point.



SURVEYOR'S SEAL

SIGNED Kenneth J. Ostling DATE 9-8-71
REGISTERED LAND SURVEYOR
10068

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68