MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T. # NR 1 T ...

					Grantang	: -	COUNTY
DESCRIPTION	OF	CORNER	Soction for	nas ėganoj	to Soots	one 6, 7,	1, 18
DESCRIPTION	OF	CORNER	MONUMENT	3º Pipe s	44 4° 20	100 909	
WIT TNESSES	то	CORNER	_120 J. Pin	o - H 25 1	i – M Kri	jà	
			20° 204 71	10 - E 97	2 - 206 L	ings	
				. .			

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Mivision survey eros, while making a partial reservey of this area. Seemer had been proviously located by an unknown Surveyor. Remains of three original B.T.'s still in place, in poor condition.

Corner was placed and witnessed April 14, 1954.

SURVEYORS SEAL

SIGNED Sear C. Sede contro DATE 12/2/34 DATE 12/2/34