

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD

CRAWFORD COUNTY


T 26 N R 3 W

DESCRIPTION OF CORNER 1/4 corner common to Sections 26 & 27

CORNER MONUMENT Set Dept. Monument

DATE MONUMENT PLACED AND WITNESSED 6-1-71

WITNESSES TO CORNER..... 7" Maple S 10 W 35.9'



6" W. Oak S 55 E 22.4'

15" W. Oak N 49 W 33.3'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division Survey Crew in 1954. They say "1 OBT in place". Dept. Mon. cap removed by unknown person. SE NBT has been destroyed. Set new monument and rewitnessed.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

*Levitt Ostling*  
REGISTERED LAND SURVEYOR

DATE

6-8-71

10068

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68