MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

			BYSHIVEL COUNTY
DESCRIPTION	OF	CORNER	-1/4 Corner between Sections 14-5-23
DESCRIPTION	OF	CORNER	MONUMENT_1"_Pipe_with_4" Proces_cop
WITTNESSES	то	CORNER	
			_ 10"_Red_Oak - # 40.V62 Make
			St_Ned Oak = S SQ R = 43 Maks

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Percetty Division survey erow, while making a partial resurvey of this Township. One original 3.7. still in place, out off below steep height. Found remains of two stakes in place, at corner.

Corner was placed and witnessed Nevember 6, 1953.

SURVEYORS SEAL

SIGNED LAND SURVEYOR DATE 1/27/54