MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T_26_ NR_3 W__

			Crawford	COUNTY
DESCRIPTION	OF	CORNER	1/4 corner common to Sections 27 &	34
DESCRIPTION	OF	CORNER	MONUMENT ** In pipe with 4" brass	cap
WITTNESSES	то	CORNER	7" B. Oak - 848W - 115 links	
			8" B. Oak - N3W - 60 links	
				·

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This cormer was established by Forestry Division survey crew, by proportionate measure, while making a partial resurvey of this township.

Corner was placed and witnessed June 15, 1955.

SURVEYORS SEAL

SIGNED LAND SURVEYOR DATE 3/8/56