

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 26. NR. 3. W. . .

Crawford

COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 28-29-32-33

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER 5" R. Oak - N30E - 18 links

7" R. Oak - S11E - 20 links

7" R. Oak - S54W - 38 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was restored by Forestry Division survey crew while completing a partial resurvey of this township. ^{Set} corner from probable SE government BT-- the only one near to conformity. Checks good for distance to corners in all directions.

Corner was placed and witnessed July 16, 1959.

SURVEYORS SEAL

SIGNED

Kenneth J. Oetting
REGISTERED LAND SURVEYOR

DATE 7/29/59