SURVEY & REMONUMENTATION

APR 0 7 1998					
SECTION LAND CORNE Filing Requi	ER RECORDATION CERTIFICATE rement of Act 74, Mich. P.A. 1970		STATE OF 1	HICHIGAN (
Crawford Locate	ed in: Corner Code #		CRAWFORD RECO	COUNTY	
1. Public Land Survey T 26N T 25	IR 4W (F-13)		19 GEC 97	•	
T T	R		SANDRA REGISTER	MOORE OF DEEDS	
2. Property Controlling S T in Section S T 3. Miscellaneous S T	R		Register of Deeds Stamp & File Number		
Property in Sec. S, Recorded Plat	-	3 P	AGE	295	л К L
I, Marvin E. Myers, in a field survey on September , 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may			5 8 19 17 17	3 9 10 16 15	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
			30 29	21 22	-232
NOTE: Not more than 2 conters, be recorded on this certificate.		13	31 32	-3334	-35
A. Description of original monument restoration:	and accessories and/or subsequent	tion			
restoration. G.L.O. April 16, 1839 H. Brevoort D.S. & James H. Mullet D.S MON: Post WIT: 20" Yellow Pine N28°W 50 links 30" Yellow Pine N81°E 10 links	Michigan Department of Conserval Billy D. Buckler; October 25, 1956 Found Both probable original BT's Found evidence of old stake point MON: 1" pipe with 4" Brass cap WIT: 5" White Oak N37°E 9 links 6" White Oak S05°E 7 links	in piace	PEFR GRO	RD COUNT OUP APPR	OVAL

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1" pipe with Conservation Department cap. Left in place. Found 8" White Oak with blaze and set nall and tag in East face N45°E 5.76' Found Pine stump N80°E 7' to face Accepted as a perpetuation of the Original Government Corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. Mon - Existing conservation Department monument left in place. THIRD WHEN THE PARTY OF THE PAR

Set nail and tag in West face 6' Red Oak N28°W 12.37' Set nail and tag in North face 4" Red Oak S68°W 13.06' Set nail and tag in East face 12" White Oak South 4.90'

Set Carsonite Post North 1'

Signed by Mario & Th Surveyor's Michigan License No. 31600

MARVIN E **MYERS** ROFESSIONA SURVEYOR

CE OF MICHIO

Marvin E. Myers, P.S. **County Surveyor**

SURVEYORS, JAN. 28, 1 REVISED MAY 14,1 REVISED JAN., 1 REVISED OCT.,

FORM APPROVED BY MICHIGAN STATE BOATH HERMIN