

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 26 NR. 4 W.

..... Crawford COUNTY

DESCRIPTION OF CORNER 1/4 corner common to Sections 3 & 10

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER

12" B. Oak - N77W - 39½ links

6" R. Pine - S60E - 51 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew while making a partial resurvey of this township. Both original BT stumps in place, the NE with good face and notch. A concrete filled tile at corner also.

Corner was placed and witnessed May 11, 1956

SURVEYORS SEAL

SIGNED Billy D. Buckles DATE 5/17/56
REGISTERED LAND SURVEYOR