

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 25 NR 4 W.
26 NR 4 W

----- Crawford ----- COUNTY

DESCRIPTION OF CORNER Corner common to Sections 4, 5, 32, 33. -----

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap, below
surface of road.

WITNESSES TO CORNER -----

8" B. Oak - N42E - 22½ links -----

7" B. Oak - N41W - 70 links -----

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED.

This corner was established by Forestry Division survey crew
while making a partial resurvey of this township. Corner was set
from probable NW original BT stump. Good corner north and east
and probable line tree stump south.

Corner was placed and witnessed Dec. 21, 1956.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 12/26/56
REGISTERED LAND SURVEYOR