

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T.26 NR. 4 W. . . .

Greerford COUNTY

DESCRIPTION OF CORNER 1/4 corner common to Sections 28 & 29

DESCRIPTION OF CORNER MONUMENT 1" pipe, with 4" brass cap

WITNESSES TO CORNER

7" R. Oak - S12W - 25 links

7" W. Oak - S66E - 39 1/2 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew while making a partial resurvey of this township. Set corner from probable original BT stump SW. This checks corners North and South, since point for proportioned corner is S55W 6 1/2 links.

Corner was placed and witnessed September 13, 1957.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 10/30/57
REGISTERED LAND SURVEYOR