MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T_26_ NR_4 W

		Crawford	COUNTY
DESCRIPTION OF CORNE	R _1/4_corner_cor	amon to Sections 2	+ and 25
DESCRIPTION OF CORNER	MONUMENTLeft	Lit pipe in plac	e
WITNESSES TO CORNER			
	6" W. Oak	850W	26½ links
	9" B. Oak	- 853E -	512 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division surveyor while searching for corners in this area. Corner had been previously established by Marcus Schaaf, Reg. Land Surveyor, in 1948, from remains of the probable government BTs.

Corner was witnessed 10/6/58

SURVEYORS SEAL

SIGNED LEMEL SURVEYOR DATE-0/7/58