MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T 26 NR 3 V ... T 26 NR 4 W

		_ Crawford	COUNTY
DESCRIPTION OF CORN	ER 1/4 corner common	to Sections 30	_and _25
DESCRIPTION OF CORNE	R MONUMENT_Left_LLT	_pipe_in_place_	
WITNESSES TO CORNER	۹		
	8" R. Oak -	N3TA	344 Tinks
	10 W. Oak -	853W -	68 links
	Center of NS fire	Line about 70 J	Links west

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was previously established by Marcus Schaaf, Reg. Land Surveyor, during a survey in 1949. Corner was restored from sites of the probable government BTs.

Corner was witnessed October 2, 1958.

SURVEYORS SEAL

SIGNED LAND SURVEYOR DATELO/7/58