

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 26 NR. 3 W.  
T 26 NR 4 W

----- Crawford ----- COUNTY

DESCRIPTION OF CORNER 1/4 corner common to Sections 19 and 24

DESCRIPTION OF CORNER MONUMENT Left 1 1/4" pipe in place

WITNESSES TO CORNER -----

7" R. Oak - S72W - 61 links  
18" R. Oak - S2W - 143 1/2 links  
Center of fireline about 125 links east.

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was previously established by Marcus Schaaf, Reg. Land Surveyor, in a survey in 1948. Corner was restored from the sites of the government BTs, during a survey of the township boundary.

Corner was witnessed for the record October 2, 1958.

SURVEYORS SEAL

SIGNED Kenneth Goethals DATE 10/7/58  
REGISTERED LAND SURVEYOR