MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T_26 NR_4W__

		Crawiord	COUNTY
DESCRIPTION OF CORNE	R S_1/S_corner_on_N-	-8_1/4_line, Sect	ion 8
DESCRIPTION OF CORNER	NONUMENT _ L" x 2	24" pipe	~
WITNESSES TO CORNER		· • • • • • • • • • • • • • • • • • • •	
	Notch in 22" W. I	ine - 860E -	7.9 feet
	9" Spruce -	NTS −	21.0 feet

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established by Forestry Division survey crew while making a subdivision of Section 8. Set corner midpoint, on line between center and South 1/4 corners. Falls about 5' south and 15.6' east of a squared stake obviously set from incomplete survey data. See map and minutes of survey of subdivision of Section 8.

Corner was placed and witnessed September 21, 1960.

SURVEYOR'S SEAL

SIGNED LAND SURVEYOR DATE 127/60