## MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

## LAND CORNER RECORD

T 26 NR 4 V

						Car	SMIOL	ī		COU	<b>NTY</b>
DESCRIPTION	OF	CORNER	1/4	corse	, comin	mito Se	ction	_18 <u> </u>	19		
DESCRIPTION	OF	CORNER	MONU	MENT.	1 <b>"</b> pg	pe, vit	h_4"_1	prese	caso _		-
WIT TNESSES	то	CORNER						·	. <b></b> -		•
			_ <b>?"</b>	Cedar	_ <b></b>	819N	_ = _	10	links		
			100	0edar	. <b></b> .	¥57¥_	- <b>=</b> -	_2 <u>6</u> 1	_links_		<del>-</del>
											-

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established by proportionate measurement between section corners, by Forestry Division survey crew while making a partial resurvey of this township. Could make no positive identification of government BT's. Check ok with stream east.

Corner was placed and witnessed September 4, 1957.

SURVEYORS SEAL

SIGNED Silly D. Buckles DATE 10/20/5>