

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 26. NR. 4. W. . .

----- Crawford ----- COUNTY

DESCRIPTION OF CORNER  $\frac{1}{4}$  corner common to Sections 25 and 26 . . .

DESCRIPTION OF CORNER MONUMENT Left  $1\frac{1}{2}$ " pipe in place . . .

WITNESSES TO CORNER -----

8" B. Oak - S32W - 43 links . . .

7" R. Oak - S80E 101 links . . .

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division surveyor while searching for corners in this area. Corner was previously established by Marcus Schaaf, Reg. Land Surveyor, in 1948, from stumps of the government BTs. Both are still in place, the SE with possible evidence of face and notch.

Corner was witnessed 10/6/58

SURVEYORS SEAL

SIGNED *Kenneth J. Ostling* DATE 10/7/58  
REGISTERED LAND SURVEYOR