

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 26 NR 4 W
26 NR 5 W

Crawford
Kalkaska COUNTY

DESCRIPTION OF CORNER Corner common to Sections 18, 19, 13, 24

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER

12" Maple - N57W - 41 links
8" Balsam - S34W - 64 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established by proportionate measure by Forestry Division survey crew while making a partial resurvey of this township. No positive evidence of original BTs. Checks good with stream crossing north and original corner ~~mark~~ south.

Corner was placed and witnessed July 5, 1956.

SURVEYORS SEAL

SIGNED Billy D. Buckles DATE 7/23/56
REGISTERED LAND SURVEYOR