

# LAND CORNER RECORDATION CERTIFICATE

## FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF--:	LOCATED IN--:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____	T. <u>27</u> N. <u>●</u> R. <u>1</u> W. <u>●</u>	A-3; A-4; B-5; C-3
2. PROPERTY CONTROLLING IN SECTION _____	, T. _____ N. _____ S. _____ R. _____ E. _____ W. _____	_____
3. MISCELLANEOUS PROPERTY IN SECTION _____	, T. _____ N. _____ S. _____ R. _____ E. _____ W. _____	_____
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Kenneth J. Ostling, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on May 27, 1975, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_, 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

- A-3 Corner previously established by County Surveyor Houghton.
- A-4 Reset Schaaf corner at midpoint on line as he intended it to be.
- B-5 Reset according to Schaaf 1935 survey record.
- C-3 Found corner as established by Schaaf in 1934.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-3	A-4	B-5	C-3
Left 4" Conc/tile monument in place	Set 1½" pipe/conc. block 8" R. Pine N42°E 19.1	Set 1½" pipe/conc. block 8" R. Pine S35°E 20.5	Left 1½" pipe/conc. base in place
12" R. Pine N89°E 28.8	10" R. Pine S65°E 18.8	10" R. Pine S25°W 35.2	7" R. Pine N81°E 7.8
8" R. Pine N40°W 24.4	Cedar Post East 10'	Cedar Post South 12'	4" R. Pine S08°E 30.6
Cedar Post SW 28'			Cedar post at corn.

SIGNED BY Kenneth J. Ostling

DATE \_\_\_\_\_

SURVEYOR'S MICHIGAN REGISTRATION NO. 10068

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

MICHIGAN REGISTERED LAND SURVEYOR



(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_