

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF--:	LOCATED IN--:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____	T. <u>27</u> ^{N.} <input checked="" type="radio"/> R. <u>1</u> ^{W.} <input checked="" type="radio"/>	<u>E-8; E-9; E-11; G-9</u>
2. PROPERTY CONTROLLING IN SECTION _____	T. _____ ^{N.} <input type="radio"/> ^{S.} <input type="radio"/> R. _____ ^{E.} <input type="radio"/> ^{W.} <input type="radio"/>	_____
3. MISCELLANEOUS PROPERTY IN SECTION _____	T. _____ ^{N.} <input type="radio"/> ^{S.} <input type="radio"/> R. _____ ^{E.} <input type="radio"/> ^{W.} <input type="radio"/>	_____
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Kenneth J. Ostling, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on May 27, 1975, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:


B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

- E-8 Found location of corner previously restored by Schaaf in 1934.
- E-9 Found corner as previously established in 1935 Schaaf survey.
- E-11 Found corner as restored in 1935 survey by Schaaf, from U.S. evidence.
- G-9 Found corner as previously restored by Marcus Schaaf from evidence of a previous survey.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-8	E-9	E-11	G-9
Set DNR monument	Set DNR monument	1½" Pipe in conc.	1½" pipe in conc.
8" J. Pine S55°E 57.3	20" R. Pine S58°W 79.8	Red-top post 28' NW	red-top post 8' W
10" J. Pine N43°E 89.1	8" R. Oak S25°E 51.0	9" R. Pine S22°E 86.6	24" R. Pine N59°W
Cedar Post West 10'	Cedar Post West 22'	8" B. Oak S56°W 25.7	10.3
			Face of power pole
			S38°W 52.4

SIGNED BY *Kenneth J. Ostling* DATE _____
 SURVEYOR'S MICHIGAN REGISTRATION NO. 10068



FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY
 APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____