## LAND CORNER RECORDATION CERTIFICATE ,

## FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -:	LOCATED IN-:	CORNER CODE NUMBE	R
1, PUBLIC LAND SURVEY8	T. <u>27                                    </u>	w. D-3 -	
2. PROPERTY CONTROLL. 8 ING IN SECTION	,T. <b>27 %</b> ., R. <b>1</b>	E. 1; 4; 5	
3. MISCELLANEOUS PROPERTY IN SECTION	N. S., R	E.   W.	
4. LOT NO, REC	ORDED PLAT		
5. PRIVATE CLAIMS	•		REGISTER OF DEEDS STAMP AND FILING NUMBER
re-established, monumented, re- and rules therefore as required i Bureau of Land Management or and 5 above were, in a field surv	mes I and 2 above were, in monumented, recovered or in the current manual of surely on a decree of a court of large on the rules of the rules of the rules of the rule of the	restored as expressed below rvey instructions of the Unit www. Furthermore, that the company, 19, found, recovered the Michigan State Board of Research	W 29.2' PW 32.5'
<ul> <li>B. Description of corner evidence Set corner mid-way at to East.</li> <li>3 Found corner in place Set by standard surve Set by standard surves by standard surves.</li> <li>C. Description of monument for 1 Set 5/8" rod w/cap a</li> </ul>	nd on line between e as established by ey procedure for su ey procedure for su corner and accessories esta	found section corner 7 E.S. Houghton 1923 abdivision of section abdivision of section abdivision of section abdivision of section ablished to perpetuate locating D-3	to West and 1/4 corner  ins.  ins.  g the position of the corner:
Jack Pine 4" S28 <sup>o</sup> Red Pine 8" S44 <sup>o</sup>	E 17.9'	ound 4" conc./tile (E Red Oak 4" N40 <sup>0</sup> E Red Oak 10" S23 <sup>0</sup> W 1 Red Oak 5" S28 <sup>0</sup> E 1	doughton Mon.) set post 4.4' 15.0' 16.2'
SIGNED BY	ATES AGENCIES:		LAND SURMINIM
			E
	MICHIGAN REGISTERED	LAND SURVEYOR	(SEAL)
SURVEYOR'S MICHIGAN REG	SISTRATION NO	···· (	crawford County