LIBER

374 PAGE

LAND CORNER RECORDATION CERTIFICATE

	Filin	g Requirement o	f Act 74, Mich. F	P.A. 1970				F. C. C. 183	0.71.4	
or corners in					,			RECUR		
Crawford	Located In:	Cor	Corner Code <i>:##</i>		6	thin	or S)	M419	<u>9 40;</u>	ιİ
(County)					9:2	Quiny	nu iN	HGER	_01	
Public Land Survey	T27N_ 1	a iw	K-13		<u></u>	E	74	! -		-
Public Land Survey	T 1				PAC	t	٠	·		
	т г					22; Register	A.Zh.A	V.Celisi	land	2
	T 8	٠				9 Davistar	of Dag	eds.		_
Property Controlling	S T I	ł		,		HoSere	01 000	,43		
In Section	s t ı	ì								
Miscellaneous	s r r			Regist	er of De	eds Sta	mp & F	File Nu	mber	
Property in Sec.	S T F	3	\							,. <u> </u>
1.44	secondard Dist									
Lot No, R				_	A B C	D €	FG	H I ,	J K	_
Private Claims					╎├╴┇╾┤		· • — —	3-1-	¹ / ₂ − -	- { -
				3	╽╌┠╼┼		+	╁┈╂━	 -	+
		Vamah	9(n 4	╎╌╏╌┼	_ 6_}	· b — —	16-1-1	ÿ - -}-	-12-
lorman C. Caldwe		March	, 19	, 5	·		-	┦—}—	├	
hereby certify that under req	uirements of P.A. 74, Mk	chigan P.A. ol 1970, ih	e corner points ment	lioned	10-10-		16	15	4	-1 3 -
tines 1 and 2 above were in trent manual of survey instru	conformance with regi	ulations and rules the	erelore as required se Interior Bureau of	in the Hand 7	·	_ _ _	↓	+	1	1
inagement or by a decree of a	Court of Law and/or the	at the corner points m	entioned in lines 3, 4	and 5		_20	21	22	23	_]
ove were in conformance will	h the rules of the Michig	an Board of Land Sur	rveyors or by a Decre	ee ola 🛴		ĭ			ĭL	Ĩ
ourt of Law; established, re	e-established, monum	ented, re-monument	ed, recovered, four	nd as "						Ţ
pressed below:	•			•	1 40	-29	28-1-	2/	26-1-	-25-
OTE: Not more than 4 co	orners, all in the sam	e town and range,	may be recorded	•						7
on this certificate.				12		-32	33 -	343	35	-36-
Description of original n	nanumant and acces	enripe and/or subs	equent restoration	13 n·	i t L			4		
			oquem representation							
(K-13) Post set	by Mullett	in 1839.								
Pine 10'	" N59°W .13	(8.58')								
Maple 6	" N59°E .10	(6,60')								
		•		•						
Description of corner ev	idence found and/or	method applied in	restorina or reest	tablishing co	rner:					
Description of comer ev	igorios rouris and/or		a block m	on from	n 2 o	ria.	BTs.			
1 AL V - P	107/ COT 8	DIDE & COD	ICA DIOCK III					4		

(K-13) LaGuire, 1934, set a pip

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(K-13) Stand. cor. 35&36, T27N-R1W

Fnd. 1/2" bar, placed 12018 cap, @ S. shoulder of private E-W road, 2 1/2' N. of steel fe. post. And is accepted as a careful & faithful perpetuation of the position of the original corner.

Carsonite Witness Post South 0.51 N35°E 29.4' 16" Poplar (old BT) S05°W 31.6' 14" Poplar (old BT) S35°W 19.8' 16" R. Pine

N50°W 47.0' 1/2" pipe & lath

12018 rveyor's Michigan License No.

NORMAN C. CALDWELL 1 DAYOD SURVEYOR FORM APPROVED TO WHAT SE 2018 H. LAW SUPERINS, JAN. 28, 1971 P. 1975 MAY 14, 1975 MAY 14, 1975 LAND SUPERINS REVISED JAN., 1983

STATE OF MICHICAN

COUNTY OF CRAWFORD