

# LAND CORNER RECORDATION CERTIFICATE

## FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF--:	LOCATED IN--:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 27 N. R. 2 W.	J-10
2. PROPERTY CONTROLLING IN SECTION 26	T. 27 N. R. 2 W.	5
3. MISCELLANEOUS PROPERTY IN SECTION 26	T. 27 N. R. 2 W.	J-9/5; 5/J-10
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND  
FILING NUMBER

I, Kenneth J. Ostling, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on September 21, 1978, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on September 20, 1978, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and for subsequent restoration:

C. (continued) 5/J-10  
 Set 5/8" rod w/RLS cap  
 10" Oak S43°W 29.95  
 14" Oak S85°W 11.95  
 Set cedar guard post

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

- J-10 Found 1/2" iron bar as established in previous survey by N. Parker. Fits all other controlling corner locations.
- 5 Set corner by standard survey procedure for the subdivision of sections.
- J-9/5 Set corner by standard survey procedure for the subdivision of sections.
- 5/J-10 Set corner by standard survey procedure for the subdivision of sections.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

J-10	5	J-9/5
Left 1/2" rod w/RLS cap in place	Set 5/8" rod w/RLS cap	Set 5/8" rod w/RLS cap & cedar post
5" R. Oak S40°W 6.95	6" Maple in clump of 8	6" W. Oak N41°W 9.9
14" R. Oak N40°W 1.6	S88°W 18.6	10" W. Oak N57°E 7.25
Set cedar guard post	12" Oak N21°E 42.5	
	Set cedar guard post	

SIGNED BY Kenneth J. Ostling

DATE 11-15-78

SURVEYOR'S MICHIGAN REGISTRATION NO. 10068



FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_

DATE \_\_\_\_\_

APPROVED AND SIGNED BY \_\_\_\_\_  
MICHIGAN REGISTERED LAND SURVEYOR

DATE \_\_\_\_\_

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_

CRAWFORD COUNTY