

✓

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 27. NR. 2. W.

----- Crawford ----- COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 25, 26, 35, 36 -----

DESCRIPTION OF CORNER MONUMENT 12" Pipe in center of road -----

WITNESSES TO CORNER 12" J. Pine - S 12 W - 41 Links -----

8" J. Pine - S 60 E - 19 Links -----

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was ~~established~~ found by Forestry Division survey crew, while making a partial resurvey of this Township. Corner had been previously located by unknown Surveyor. One original B.T. still in place, in fair condition.

Corner was placed and witnessed June 15, 1954.

SURVEYORS SEAL

SIGNED Alan C. St. Peter DATE 12/2/54  
REGISTERED LAND SURVEYOR