

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 27. NR. 3 W.

Crawford COUNTY

DESCRIPTION OF CORNER Corner common to Sections 20, 21, 28, 29

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER

<u>10" R. Pine</u>	<u>-</u>	<u>N63W</u>	<u>-</u>	<u>116½ links</u>
<u>6" Aspen</u>	<u>-</u>	<u>N43E</u>	<u>-</u>	<u>62 links</u>
<u>8" W. Oak</u>	<u>-</u>	<u>S16E</u>	<u>-</u>	<u>168½ links</u>

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew while making a search for corners in this township. Corner had been previously established by Marcus Schaaf, Registered Land Surveyor around 1934. Both original BT stumps in place with good faces.

Corner was placed and witnessed Sept. 5 1956

SURVEYORS SEAL

SIGNED

*Billy D. Buebler*

REGISTERED LAND SURVEYOR

DATE 11/19/56