

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


CRAWFORD COUNTY
T 27 N R 3 W

DESCRIPTION OF CORNER 1/4 corner common to Sections 21 - 22

CORNER MONUMENT Set Dept. Monument

DATE MONUMENT PLACED AND WITNESSED 6-1-71

WITNESSES TO CORNER..... GLO stp 10" R.P. Stp: N 4 E 12.5'



" " 16" W.P. Stp. S 15 E 1.3'

Old NBT 10" J.Pine N 72 E 23.5'

AND " " 9" J.Pine S 30 W 14.2'

" " 11" R. Pine N 38 W 34.2'

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Survey Crew. M. Schaaf set pipe in block of concrete, we replaced his pipe with a Dept. Monument.

OBT stumps still in place. NE with good face. (G.L.O. N 5° W); SE with partial face.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

Kevin J. Ostling
REGISTERED LAND SURVEYOR

DATE

6-8-71

10068

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68