

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 27. NR. 3. W. .

----- Crawford ----- COUNTY

DESCRIPTION OF CORNER Corner common to Sections 13, 14, 23, 24 . . .

DESCRIPTION OF CORNER MONUMENT 1 1/2" pipe with concrete base . . .

WITNESSES TO CORNER 7" B. Oak - S33E - 65 links . . .

9" W. Oak - N33E - 68 links . . .

Park Mon. - S29E - 41 links . . .

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED.

This corner had been previously established by Marcus
Schaaf, Registered Land Surveyor, from original BT stumps.
Stumps of the old BTs are still in place in good condition (wit-
nesses to the old effaced corner)

Corner was witnessed Oct. 31, 1956.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 11/19/56
REGISTERED LAND SURVEYOR