

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 27. NR. 3 W.

..... Crawford COUNTY

DESCRIPTION OF CORNER 1/4 corner common to Sections 33 & 34

DESCRIPTION OF CORNER MONUMENT 2"x14" iron bar

WITNESSES TO CORNER

8" Tamarack - - - N10W - - - 176 links.

12" Double Oak - - - S86E - - - 63 links.

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED.

This corner was found by Forestry Division survey crew while making a search for corners in this township. Corner had been previously established by Marcus Schaaf, Registered Land Surveyor. Corner tree stump in place, and the NW original BT stump in place with partial face. Large hole and roots for SE stump.

Corner was set and witnessed Oct. 31, 1956.

SURVEYORS SEAL

SIGNED Billy D. Buckler .. DATE 11/19/56
REGISTERED LAND SURVEYOR