

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Crawford County
County

Located In:

Corner Code //

- | | | | | | | |
|---|---------------------------------|---|-----|---|----|-------|
| 1 | Public Land Survey | T | 27N | R | 3W | F-10; |
| | | T | 27N | R | 3W | F-9 |
| | | T | | R | | |
| | | T | | R | | |
| 2 | Property Controlling in Section | S | T | R | | |
| | | S | T | R | | |
| 3 | Miscellaneous Property in Sec. | S | T | R | | |
| | | S | T | R | | |

4. Lot No _____, Recorded Plat _____
 5. Private Claims _____

Register of Deeds Stamp & File Number

I, **Carl R. Johnson**, in a field survey on **March 11**, 19 **86**, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A Description of original monument and accessories and/or subsequent restoration:

B Description of corner evidence found and/or method applied in restoring or reestablishing corner.

F-10 - Found corner in place from previous recorded survey.

F-9 - Found corner in place from previous recorded survey.

C Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F-10			F-9		
12" Red Pine	N24°W	89.2'	Found ½" rod in conc. set cedar post		
10" Red Pine	N24°E	50.5'	6" Jack Pine	S19°W	19.5'
6" Maple	S50°W	20.4'	6" Jack Pine	S68°E	14.6'

(Found 1½" pipe)

Signed by 
 Surveyor's Michigan License No. **30083**

Date **6/5/86**

