

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

CRAWFORD COUNTY


T 27 N R 4 W

DESCRIPTION OF CORNER SW corner Section 10

CORNER MONUMENT Set Dept. Monument

DATE MONUMENT PLACED AND WITNESSED 10-15-71

WITNESSES TO CORNER..... 8" R. Oak N 65 W 1.9'



6" W. Oak S 35 E 24.1'

18" Y. Pine Stp. S 23 W 34.1'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

U.S.B.T - Y. Pine 14 - S 27 W, 26 lks.

Stump in place with good face.

Corner was set from stump of U.S.B.T., which is in place with good face. A 3/4" pipe is located about 3' North and 15' East, apparently erroneous.



SURVEYOR'S SEAL

SIGNED

Kenneth J. Ostling
REGISTERED LAND SURVEYOR
10068

DATE 10-22-71

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68