## STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

## LAND CORNER RECORD

		CRAWFORD		COUNTY			
		τ	27	N	R _	4	W
DESCRIPTION OF CORNER _	W 1/4 corner, Section 10						
CORNER MONUMENT	Set DNR Monument			<u> </u>		<u></u>	
DATE MONUMENT PLACED AND	WITNESSED	10-19-7	1				
WITNESSES TO CORNER							
N	6" Tw. R. Oak	N 64 E		<u></u>		21.9'	
0		S 22 W				22.1	<u> </u>
CIRCLE CORNER REGISTER	AND ED						

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

U.S.B.T. 20" W. Pine N 55 E 8 lks.

Corner restored from stump of U.S.B.T., which is in place with partial face and notch.

, res	ATE OF MICK	79.
REGISTAL	KENNETH J. OSTLING LAND SURVEYOR No.	GAN * 40,11
•	LAND SURVEYOR'S	SEAL

SIGNED REGISTERED LAND SURVEYOR 18068

10-26-71

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing