## MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

## LAND CORNER RECORD

27 5 W T\_27. NR\_5\_W\_\_\_

Crantord - Kajkaska COUNTY
DESCRIPTION OF CORNER 1/4 corner common to Sections 19 & 24
DESCRIPTION OF CORNER MONUMENT 1" pipe, with 4" brass cap
WITTNESSES TO CORNER
12" J. Pine - WW - 27 links
12" J. Pine - S58W - 05\frac{1}{2} links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established by proportionate measurement between section corners north and south by Forestry Division survey crew while making a survey of Section 19. No original evidence. Set midpoint on line between previously established section corners.

Corner was placed and witnessed May 24, 1957

SURVEYORS SEAL

SIGNED Silly & Suchles DATE 1/26/57